

R012345  
 10/4/17 11:15 AM  
 Al Leinmont  
 4321 Main St.  
 Cambertown, TN 38467  
 aleinmont@email.com  
 Tel: (H) 491-555-9876




**HUNTER**  
 Engineering Company

11250 Hunter Drive  
 Bridgeton, MO 63044  
 Tel: (314) 731-3020

**Chrysler : 200 : 2015-17 : Front Wheel Drive  
 ExpressAlign Total Alignment**



**Wheel Alignment**



**Safety System Alignment®**

**COMPLETE**

Required OEM procedures performed according to vehicle service documentation.

**Before**

**Current**

<b>(EPS) Electric Power Steering</b> $+0.3^\circ$	<b>(EPS) Electric Power Steering</b> $+0.0^\circ$
<b>(ACC) Adaptive Cruise Control</b> $-0.487^\circ$	<b>(ACC) Adaptive Cruise Control</b> $+0.010^\circ$

• One or more values are not within specification. Tire wear, handling and safety problems may result.

Customer concern was a pull to the right at highway speeds. Replaced electric power steering rack and performed alignment. Road tested to verify operation of steering rack, no pull was noticed.